

ON 01/18

(This is a reprint of Operating Notice 01/17 issued 27Feb2017)

Variations from the 2003 General Appendix

2.6.2.7 **Fires in Buildings at Pendre**

The link from the Pendre fire alarm to the Fire Service is no longer operational. Measures already being taken to avoid false alarms should be continued.

4.2 (l)(1) **Pendre Local Instructions**

Visual Indications are not fitted to the train approach indicators, but the audible warnings have different pitches for up and down trains.

D J Scotson
Operating Manager
06 February 2018

DJS/PMK