

ON 22/18

(This is reprint of Operating Notice 23/17 Issued 27Feb2017)

Shunting into Section without a Token

Shunting into Section without a Token is now **PROHIBITED**

The following Rules and Regulations, and references to them are **cancelled**

Rule Book Appendix 1 (Summary of Train Signalling Regulations for Train Crews)

*Signalling Regulation 7B (Shunting without a Token)

*Signalling Regulation 9B (Engineering trains working in section) paragraph 2

*References to these Regulations in Rules B.3(b) and C.10

Instructions to Blockmen

Regulation D: Bell Signals 3-3-2 and 8

Signalling Regulation 7B (Shunting without a Token)

Signalling Regulation 9B (Engineering Trains working in section) paragraph (b)

Any circumstance in which the absence of this facility significantly hinders the working of the Railway should be reported to management.

D J Scotson
Operating Manager
06 February 2018

DJS/RMW